





ULTIMATE ELEMENTOR INSTRUCTIONS



1 Cut model parts along the SOLID lines.



2 Fold along the DOTTED lines.
Fold and glue tabs in number order.



3 When each piece is dry, glue them together as shown (match the colors).



4 GO TURBO!!!

CUT

MOUNTAIN FOLD

VALLEY FOLD

